Entry PD42 Outside drawing





Connector Layout